

ADEQ Complaints and Inspections

Computer Services Division

Patrick Stair - (501) 682-0673

Search Form

Please make your selection(s), then click the "Search" button. All fields left "blank" or "No Restrictions" returns the complete list. AFIN, Permit Number, Facility Name, Insp/Complaint number, Name/Address and City are matched if the record contains what you enter. The Miscellaneous Search field matches on a "contains" search against the Complaint/Inspection description, Complaint/Inspection location, Complaint/Inspection Comment, and Name/Address fields in the master record. All other fields are matched if the record equals what you enter.

Complaint/Inspection Information

Insp/Complaint
Number:

Search Type

☐ Complaints

Name/Address:

☐ Inspections

County:

☐ Both

City:

☐ Inspections With Violations

Miscellaneous Search:

Facility/Permit Information

AFIN:

(Must enter dash, XX-XXXXX)

Permit
Number:

(Digits, Letters, & Dashes only)

Media:

[Facility and Permit Information \(PDS\)](#)

Date Range

Start
Date: (mm/dd/yyyy)

End
Date: (mm/dd/yyyy)

Search

Reset

Download

[Download a zipped copy of the full Access 2000 Database](#)
(CompInsp_web.zip Approximate file size: 14.5 MB)

Note: These data files are updated nightly.

Complaints and Inspections

AFIN	Permit Number	Comp/ Insp No.	Name/Address	Date	Media
Recs Found: 11	<< ≤	Page 1 /1 ≥ >>	Records Per Page: 1 5 10 20 30 40 50 100	Export Query	
15-00000		045038 (I)	DESOTO GATHERING STAA BRINDLEY CREEK P.O. BOX 789 CONWAY County: Conway	4/9/2009	W
INSPECTION CONCERNS: The right-of-way has been cleared and trenching was in progress at the time of this inspection. Sediment reducing BMPs had not been installed prior to beginning the project. Some downstream sediment deposits were noted but did not appear significant.					
15-00528	1868-AGP-092	037811 (I)	DESOTO GATHERING/S.BROWN IE #1 3 M NE OF HATTIEVILLE HATTIEVILLE County: Conway	1/24/2008	A
INSPECTION CONCERNS: Specific Condition #9: Failure to test fuel gas within 30 days of permit issuance. INSPECTION COMMENT: Informal Enforcement Action Response letter received 03/06/2008. A letter reporting the facility corrective action was adequate was mailed 03/20/2008.					
15-00580	1868-AGP-127	042830 (I)	DESOTO GATHERING/G.HILL	11/19/2008	A

AFIN	Permit Number	Comp/ Insp No.	Name/Address	Date	Media
			CPF 3 HWY 124 & SHEEPSKIN RD, T/N FOR 4.5/M-T/SW @ LSE RD FOR 1/M CENTER RIDGE County: Conway		

INSPECTION CONCERNS: SC#29- Initial Notifications were received on July 22, 2008. Engine 4ZS00839 was the only engine at this facility that this Initial Notification was received in time. Engines 4ZS00925 and 4ZS00858 were late. The Initial Notification for engines 4ZS00925 and 4ZS00858 were due on 4/18/2008, but were received on 7/22/2008. SC#33- DeSoto Gathering failed to meet the requirements of 40 CFR part 60 subpart JJJJ, notification requirements listed in 60.4245(c). Therefore is out of compliance with this condition. INSPECTION COMMENT: None

23-00896	1868-AGP-097	037831 (I)	DESOTO GATHERING/QUITMAN CPF1 2 MILES SE OF QUITMAN QUITMAN County: Faulkner	1/24/2008	A
--------------------------	------------------------------	----------------------------	---	-----------	---

INSPECTION CONCERNS: Exceeded emission limit of Specific Condition 2. INSPECTION COMMENT: Informal action. Response letter received 03/12/2008. A corrective action was adequate letter was mailed 03/20/2008.

58-00766	1868-AGP-149	060096 (I)	DESOTO GATHERING/MATHIS HOLLOW ATKINS-N ON 105 18 MILES, T/R @ W. OAK MTN RD TO LSE RD-L/S HECTOR County: Pope	7/12/2011	A
--------------------------	------------------------------	----------------------------	--	-----------	---

INSPECTION CONCERNS: The facility was granted an initial GOP on May 30, 2008. On December 22, 2010 the facility submitted a NOI for coverage under the new General Operating Permit for Minor Source Natural Gas Compression Stations that was issued on December 14, 2010. The previous GOP for Gas Gathering Stations expired on March 17, 2010. Therefore, DeSoto Gathering Company - Mathis Hollow CPF-1 was operating without an air permit from March 17, 2010 until December 22, 2010. Regulation No. 19 19.401 states: No person shall cause or permit the operation, construction, or modification of a stationary source, whose actual emissions are: 75

AFIN	Permit Number	Comp/ Insp No.	Name/Address	Date	Media
<p>tpy or more of CO; 40 tpy or more of NOX, 40 tpy or more of SO2 40 tpy or more of VOCs; 15 tpy or more of PM10; 0.5 tpy of lead; 2.0 tpy or more of any combination of HAPs without first obtaining a permit from the Department pursuant to the provisions of this chapter. Arkansas Code 8-4-310 states: (a) It shall be unlawful and constitute a misdemeanor: (2) To construct, install, use, or operate any source capable of emitting air contaminants without having first obtained a permit to do so, if required by the regulations of the Arkansas Pollution Control and Ecology Commission, or to do so contrary to the provisions of any permit issued by the Arkansas Department of Environmental Quality or after any such permit has been suspended or revoked. Specific Condition 31: Regarding the Initial JJJJ Notification, Mr. Darren Jones stated that WPW02176 is a leased engine from CDM and that DeSoto Gathering ordered the engine on 6/30/2008 and the JJJJ notification was received by ADEQ on 8/13/2008; therefore, fourteen (14) days after the required thirty (30) day timeframe. Specific Condition 31 states: A permittee with a stationary SI ICE greater than or equal to 500 HP that has not been certified by an engine manufacturer to meet the emissions standards in [40 CFR 60 Subpart JJJJ] 60.4231 must submit an initial notification as required in 60.7(a)(1). The notification must include the information below: i) Name and address of the permittee; ii) The address of the affected source; iii) Engine information including make, model, engine family, serial number, model year, maximum engine power, and engine displacement; iv) Emission control equipment; and v) Fuel used. As stated in 60.7(a)(1): Any owner or operator subject to the provisions of this part shall furnish the Administrator written notification as follows: A notification of the date construction of an affected facility is commenced postmarked no later than 30 days after such date. 40 CFR 60 Subpart JJJJ 60.4230 states: For the purposes of this subpart, the date construction commences is the date the engine is ordered by the owner or operator. INSPECTION COMMENT: None</p>					
60-01545		050768 (I)	DESOTO SAND, LLC 200-B SAND RIVER RD 1.5 MILES SE OF I-440 & HWY 70 NORTH LITTLE ROCK County: Pulaski	2/22/2010	WN
INSPECTION CONCERNS: Not implementing stormwater SWPPP, insufficient BMPs in place, discharging to waters of the state.					
60-01545	ARR000738	063064 (I)	DESOTO SAND, LLC 200-B SAND RIVER RD 1.5 MILES SE OF I-440 & HWY 70 NORTH LITTLE ROCK County: Pulaski	12/21/2011	WS
INSPECTION CONCERNS: 1. This facility continues to operate an Industrial Sand Washing Operation without a valid NPDES Permit. This violation was first noted during a complaint investigation I performed on February 22, 2010. An application for the appropriate permit has been received by the Department and deemed complete. This operation was not discharging on the date of the inspection. This is a violation of the Arkansas Water and Air Pollution Control Act (A.C.A. 8-4-217(b)(1)(A)). 2. This facility has a small wastewater treatment system that discharges to the waters of the state without a valid permit. Additionally, on the date of the inspection a small					

AFIN	Permit Number	Comp/ Insp No.	Name/Address	Date	Media
sewer leak was noted that was discharging to the waters of the state. This is a violation of the Arkansas Water and Air Pollution Control Act (A.C.A. 8-4-217(b)(1)(A)) and (A.C.A. 8-4-217(b)(1)(E)). INSPECTION COMMENT: ARR000738 - The following violations of the General Permit for the Discharge of Stormwater from Industrial Activities were noted: 1. The number and location of stormwater outfalls is not consistent with those included on the Notice of Intent for this facility. During the inspection, outfalls on the north side of the property near the small wastewater treatment plant were noted. Stockpiles of sand, an old equipment laydown yard, and a wastewater plant were noted in this area. (See attached Satellite view for the general location of the stormwater outfalls). 2. The Permit in Part 4.6.6.7 requires erosion to be addressed in the SWPPP. Part 6.6 in the SWPPP only briefly addresses erosion issues. During the inspection, significant erosion gullies were noted in proximity to the small wastewater treatment plant and material stockpiles were noted adjacent to the waters of the state. The SWPPP needs to be updated to better address erosion issues and they should be included as part of the required site inspections. 3. Appropriate records of the measureable storm event and sampling were not being kept in accordance with Part 3.7.2.e of the permit. 4. The samples collected in					
60-01545	ARR152927	063065 (I)	DESOTO SAND, LLC 200-B SAND RIVER RD 1.5 MILES SE OF I-440 & HWY 70 NORTH LITTLE ROCK County: Pulaski	12/21/2011	W
INSPECTION CONCERNS: This permit expired on October 31, 2011 and has not been renewed even though construction activities are still ongoing at this facility. Under the conditions of the permit, you have until January 31, 2012, to obtain the renewal permit and fully implement the changes in the newly reissued permit. 1. The stormwater pollution prevention plan (SWPPP) is not properly signed as required by Part II, B.1.B of the permit. The contractor and inspector certifications were not signed. 2. The stormwater pollution prevention plan (SWPPP) is not being updated as required by Part II, A. 3 of the permit. Silt fences have been removed but the SWPPP was not updated to indicate the removal of the fences. Additionally, the inspection form being used on site is not the same one that was in the SWPPP. 3. The inspection forms being used onsite do not meet the requirements of Part II, A.4.M.2 of the permit. The one currently in the SWPPP does meet the requirements of the permit but it is not being used. The form currently being used does not include: the inspector's title, the inspector's signature, and the locations and dates when major construction activities begin, occur or cease. It should be noted that the form currently in the SWPPP does not contain all the elements required by the recently renewed permit. A copy of an inspection form that meets the requirements of the new permit can be obtained on ADEQ's web site. 4. Not all stormwater controls have been installed as described in the SWPPP as required by Part II, A.4.H of the permit. There are controls indicated on the site map that are no longer in place.					
63-00818	ARR00C009	048238 (I)	COOPER CONCRETE HWY 5 & DESOTO BLVD 9 HOT SPRINGS VILLAGE County: Saline	9/25/200	WN
INSPECTION CONCERNS: 1. There were multiple locations that discharged off-site. When stormwater comes into contact with process waste, the water then is classified as process wastewater, which is subject to individual					

AFIN	Permit Number	Comp/ Insp No.	Name/Address	Date	Media
------	---------------	----------------	--------------	------	-------

NPDES permitting. 2. Permittee performs a comprehensive inspection annually, but routine inspections are not being performed to ensure continued compliance.

71-00000		044918 (I)	SEECO, INC. GRAVES 2-26 RPA #2008213 23 NABCO AVE CONWAY County: Van Buren	4/1/2009	WS
--------------------------	--	----------------------------	--	----------	----

INSPECTION CONCERNS: April 6, 2009 George Sheffer, Desoto Field Manager Seeco, Inc. 23 Nabco Avenue Conway, AR 72032 RE: Graves 2-26, Reserve Pit# 2008213, Van Buren County, Arkansas Dear Mr. Sheffer: On April 1, 2009, I performed an inspection of the above referenced drilling site in accordance with the provisions of the Arkansas Water and Air Pollution Control Act and the regulations promulgated thereunder. The inspection revealed the following: The poor erosion control effort around the drilling pad and pipeline is considered placing waste in a location that is likely to cause pollution to wa

73-00987	1868-AGP-129	042841 (I)	DESOTO GATHERING/TIGER CPF-1 HWY 167 & 919,T/W TO WALLIS RD GO .75/M TO LSE RD, GO 1/M S JUDSONIA County: White	11/21/2008	A
--------------------------	------------------------------	----------------------------	---	------------	---

INSPECTION CONCERNS: Failure to submit NSPS Subpart JJJJ initial notification on time.



[Send Us Feedback](#)
[Take our 1 Minute Web Survey](#)



[ADEQ Helpline: \(501\) 682-0923](#)

[Privacy Statement](#)

[Legal Disclaimer](#)

[Accessibility](#)

[About PDF™](#)

